

## River water quality: A case study of Yamuna at Allahabad

## ■ IBADAIAHUN MYRTHONG, RICHA SHARMA, GIDEON SYNREM AND SUSHIL KUMAR

Article Chronicle:
Received:
15.05.2014;
Accepted:
29.05.2014

**SUMMARY:** Rivers are an indispensable part of our biosphere which is essential for the overall development of the present civilization. The present study was focused on the different areas of the River Yamuna at Allahabad city. Sampling and analysis was conducted as per the guidelines of CPCB. The results revealed that there was significant difference in months due to the variations in temperature, weather conditions and even rainfall but there was no significant difference between the sites. The results revealed that the water was suitable for irrigation purpose as the values were found to be within the permissible limit except for DO whose values were found to be slightly less than the permissible limit which makes it unsuitable for bathing purpose. Data shows that the water quality of Yamuna river falls under C category of the surface water quality criteria by CPCB.

**HOW TO CITE THIS ARTICLE:** River water quality: A case study of Yamuna at Allahabad (2014). River water quality: A case study of Yamuna at Allahabad. *Asian J. Environ. Sci.*, **9**(1): 62-67.

Key Words:
DO, CPCB,
Irrigation, C category

 $\boldsymbol{Author}$  for correspondence :

## IBADAIAHUN MYRTHONG

Department of Environmental Science, Sam Higginbottom Institute of Agriculture, Technology and Sciences, ALLAHABAD (U.P.) INDIA Email: imyrthong644@ gmail.com

See end of the article for Coopted authors'